

JT9D-59A, -70A, -7Q, and -7Q3 engines, accomplish the following:

(1) Disks that have not been fluorescent penetrant inspected or eddy current inspected since introduction into service, perform an initial fluorescent penetrant inspection (FPI) for cracks in all 40 cooling air holes in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using Special Process Operation Procedure (SPOP) 84, as follows:

(i) Disks with 3,500 cycles since new (CSN) or more on the effective date of this AD, inspect prior to accumulating 5,000 CSN, or within 1,500 cycles in service (CIS) after the effective date of this AD, whichever occurs later.

(ii) Disks with less than 3,500 CSN on the effective date of this AD, inspect prior to accumulating 5,000 CSN.

(2) Disks that have been reoperated in accordance with PW SB No. 5815, Revision 2, dated July 31, 1992, or prior revisions, that have not been fluorescent penetrant inspected or eddy current inspected since reoperation, perform an initial FPI for cracks in all 40 cooling air holes in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84, as follows:

(i) Disks with 3,500 CIS or more since reoperation on the effective date of this AD, inspect prior to accumulating 5,000 CIS since reoperation, or within 1,500 CIS after the effective date of this AD, whichever occurs later.

(ii) Disks with less than 3,500 CIS since reoperation on the effective date of this AD, inspect prior to accumulating 5,000 CIS since reoperation.

(3) Disks that have been fluorescent penetrant inspected, or eddy current inspected, since introduction into service or since re-operation, in accordance with PW SB No. 5744, Revision 3, dated March 31, 1993, or prior revisions, or PW JT9D-7Q, -7Q3 Engine Manual, P/N 777210, 72-51-00, Inspection -03, or PW JT9D-59A, -70A Engine Manual, P/N 754459, 72-51-00, Heavy Maintenance Check -03, perform an FPI for cracks in all 40 cooling air holes, prior to accumulating 3,500 CIS since last FPI or ECI, or within 250 CIS after the effective date of this AD, whichever occurs later, in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84.

(4) Thereafter, perform FPI for cracks in all 40 cooling air holes at intervals not to exceed 3,500 CIS since last FPI, in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84.

(5) Prior to further flight, remove from service cracked disks, and replace with serviceable parts.

(b) For second stage HPT disks, P/N 5001802-01, installed in PW JT9D-7R4D, -7R4D1, 7R4E, and -7R4E1 (AI-500) engines, accomplish the following:

(1) Disks that have not been fluorescent penetrant inspected since introduction into service, perform an initial FPI for cracks in all 30 tie bolt holes in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84, as follows:

(i) Disks with 6,000 CSN or more on the effective date of this AD, inspect prior to accumulating 8,000 CSN, or within 2,000 CIS after the effective date of this AD, whichever occurs later.

(ii) Disks with less than 6,000 CSN on the effective date of this AD, inspect prior to accumulating 8,000 CSN.

(2) Disks that have been fluorescent penetrant inspected since introduction into service, perform an FPI for cracks in all 30 tie bolt holes, prior to accumulating 6,000 CIS since last FPI, or within 250 CIS after the effective date of this AD, whichever occurs later, in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84.

(3) Thereafter, perform FPI for cracks in all 30 tie bolt holes at intervals not to exceed 6,000 CIS since last FPI, in accordance with PW Turbojet Engine Standard Practices Manual, P/N 585005, Chapter/Section 70-33, using SPOP 84.

(4) Prior to further flight, remove from service cracked disks, and replace with serviceable parts.

(c) Report findings of cracked turbine disks within 48 hours after inspection to Daniel Kerman, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (617) 238-7130, fax (617) 238-7199, Internet: "Daniel.Kerman@faa.dot.gov". Reporting requirements have been approved by the Office of Management and Budget and assigned OMB control number 2120-0056.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the inspection requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on March 13, 1997.

James C. Jones,

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 97-6889 Filed 3-18-97; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Part 1

[REG-249819-96, REG-209762-95]

RIN 1545-AU67, 1545-AT32

### Reorganizations; Receipt of Securities and Allocations of Depreciation Recapture Among Partners in a Partnership; Hearing Cancellation

**AGENCY:** Internal Revenue Service, Treasury.

**ACTION:** Cancellation of notices of public hearing on proposed rulemaking.

**SUMMARY:** This document provides notice of cancellation of public hearings on proposed regulations relating to the receipt, as part of a reorganization, of rights to acquire stock of a corporation that is a party to the reorganization and the allocation of depreciation recapture among partners in a partnership.

**DATES:** The public hearings originally scheduled for March 25, 1997, and March 27, 1997, respectively, beginning at 10 a.m., are cancelled.

**FOR FURTHER INFORMATION CONTACT:** Evangelista C. Lee of the Regulations Unit, Assistant Chief Counsel (Corporate), (202) 622-7190 (not a toll free number).

**SUPPLEMENTARY INFORMATION:** The subject of the public hearings is proposed amendments to the Income Tax Regulations under sections 354, 355, 356, 704 and 1245 of the Internal Revenue Code. A notice of public hearing appearing in the Federal Register on Monday, December 23, 1996 (61 FR 67508) and Thursday, December 12, 1996 (61 FR 65371), announced that a public hearing would be held on Tuesday, March 25, 1997, and Thursday, March 27, 1997, beginning at 10 a.m., in room 3313, Internal Revenue Building, 1111 Constitution Avenue, NW, Washington, DC 20224.

The public hearings scheduled for Tuesday, March 25, 1997, and Thursday, March 27, 1997, respectively, are cancelled.

Cynthia E. Grigsby,

*Chief, Regulations Unit, Assistant Chief Counsel (Corporate).*

[FR Doc. 97-6891 Filed 3-18-97; 8:45 am]

BILLING CODE 4830-01-U